



JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT

Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

September 7, 2007

Supervisor DRZ

**Mine Name:** Haas Limestone-Gunnison

**Operator Name:** Bryce Haas.

**Permit number:** S/039/012

**Inspection Date:** August 29, 2007

**Time:** 11:45 am

**Inspector(s):** Lynn Kunzler, DOGM

**Other Participants:** Bryce Haas

**Mine Status:** Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Routine inspection while in the area.

#### Inspection Summary:

This site has been inactive for over a year. There was no evidence that there has been any activity at this site this year. Currently, the operator has not provided a reclamation surety for this site, he has been told that there is to be no activity, other than reclamation work, until the surety is provided. The operator is intending to send the Division a letter requesting the bonding requirement be waived until such time that he re-activates this site.

#### Conclusions and Recommendations:

Continue to monitor this site when in the area.

**Inspector's Signature**

LK:pb

O:\M039-Sanpete\S0390012-HaasLimestone-gunnison\inspections\Insp-08292007.doc